

C6. ENVIRONMENTAL SETTING at 3990 Laughlin Road, Windsor CA 95492 June 6, 2008
Immediately downstream from the proposed point of diversion.



Toe of embankment. View East showing no channel, mowed grass and oak trees at property line.



Continuation of above towards south. View East from property line. No channel, disced vineyard in adjoining property.

C6. ENVIRONMENTAL SETTING at 3990 Laughlin Road, Windsor CA 95492 June 6, 2008
Immediately upstream from the proposed point of diversion.



View N through vineyard to Laughlin Road from upslope end of impoundment. Watershed limit at horizon. Culvert w armored outfall under vineyard road. Sheet flow only through vineyard.



View S to impoundment in trees from culvert outfall seen above. Note sheet flow only between culvert and pond. Vegetation: vineyard, lawn, landscape willows, oaks, conifers. Wasp trap in air.

C6. ENVIRONMENTAL SETTING at 3990 Laughlin Road, Windsor CA 95492 June 6, 2008

At the place(s) where the water is to be used.



Typical vineyard setting at POU showing Laughlin Road, landscaping olive trees, grass-covered avenue, and wine grape vineyard. Impoundment about 350' downslope to left.



Distorted perspective four-photo panorama from POD at center of embankment to North on longitudinal axis of 5-acre impoundment showing POU for fish and wildlife enhancement, recreation, fire suppression and landscape irrigation needs. Group use area with dock, lawn, picnic site in trees to right. Per archival aerial photos, the site was a dry annual grassland swale in 1952 with no trees, shrubs, or water present.